

Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This notice must be filed with the appropriate State or Federal agency. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

Pub. Aff. 82

New Site
High Hazard = 759 (OR 000 001 032)

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Owens-Corning Fiberglas Corporation
Street Fiberglas Tower
City Toledo State Ohio Zip Code 43659

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Owens-Corning Fiberglas Corporation
Street Old Portland Road
City St. Helens County State OR Zip Code 97051

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) William L. Kreutz, Esquire
Phone (419) 248-8220

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1930 To (Year) Present

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☐ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☒ Unknown
11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☒ Other (Specify)

Mfg. Wood Fiber

Products

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

RECEIVED

JUN 15 '81

EPA Region X

USEPA SF



1443751

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☒ Other (Specify) Wastewater Treatment

Total Facility Waste Amount
See site description
(Section I)

cubic feet

Total Facility Area

gallons

square feet
See site description below
(Section I)

acres

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☒ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Information on the hazardous waste activity at the St. Helens Plant is quite sketchy. There were apparently small amounts of various chemical materials which have been used at the Plant over the years that may have entered the water systems through the fabrication process or intentional discharge. The wastewater treatment operation would then process the water

for eventual reuse as process make-up water or it would be discharged to the Scappose Bay where it is regulated by an N.P.D.E.S. permit. Sludge from the lagoon has been disposed of within the approval of the Oregon Department of Environmental Quality.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name William L. Kreutz, Esquire
Owens-Corning Fiberglas Corporation
Street Fiberglas Tower
City Toledo State Ohio Zip Code 43659
Signature W L Kreutz Date 6-9-81

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other

High HAZARD

New Site

SCORE 117 (75%)

REVIEWED BY: EIT

DATE: 7-1-81

ATTACHMENT II

SITE NAME: Owens-Corning Fiberglass Corporation
St. Helens, Or.

IS THIS SITE ON UHWS LOG?

YES _____

NO ☒ _____

UNKNOWN _____

IF YES, IS THIS DATA CONSISTENT WITH UHWS DATA?

A) YES _____

B) NO _____ (IF NO, EXPLAIN) _____

B) DOES UHWS SHOW SITE(S) NOT DISCLOSED BY OWNER?

YES _____ (PROVIDE DETAILS) _____

NO _____

C) DOES OWNER LIST SITES NOT DISCLOSED THRU UHWS INVESTIGATION?

YES _____ (PROVIDE DETAILS) _____

NO _____

COMMENTS/SUGGESTIONS FOR FURTHER ACTION (IF ANY) _____

SCORE:	Waste (#10, assume 1,2) = 11		
	Volume (known / unknown long time ops) = 6	x	<u>66</u>
	Sensitive	=		<u>18</u>
	Release	=		<u>18</u>
		TOTAL		<u>102</u>

(possible leachate from treatment system over long period of time)

Bonus Points (15)

TOTAL

117 (75%)

HIGH HAZARD